

# MYRA 300 Polyphase Kilowatt Hour Meter

## Selection Guide

Product Code	Output Configuration	System Configuration	Cutout	Auxiliary Supply
R-Myra-300-****	w/o pulse	3P3W, 3P4W Single Phase	96 x 96	230 Vac
R-Myra-300-P-****	c/w pulse			

## Ordering format

Example

R - Myra-300 - 0060

R - Myra-300 - P - 0060



\*\*\*\* = CT primary

0001=1A	0600=600A	3000=3000A
0060=60A	0800=0800A	3200=3200A
0100=100A	1000=1000A	3500=3500A
0150=150A	1200=1200A	4000=4000A
0200=200A	1500=1500A	4500=4500A
0250=250A	1600=1600A	5000=5000A
0300=300A	2000=2000A	5500=5500A
0400=400A	2400=2400A	6000=6000A
0500=500A	2500=2500A	